



HSF




No. 1: 产品装入真空盒内 (XXPCS/盒)
SB-31AB: 235*185*12mm真空盒




No. 2: 盖上盒盖




No. 3: 贴真空盒标签




No. 6: 打包装带



No. 5: 封箱及贴纸箱标签



贴外箱标签及ROHS标签



No. 4: 真空盒装入纸箱 (20盒/箱)
纸箱上下加入纸护板
CTN-05K (双坑K=K, 40*26.5*16.5CM)

说明:

1. 产品如图所示型态放入真空盘
2. 注意各标签样式、位置及方向的一致性;
3. 打外箱包装带时需注意, 打为十字型。

变更
记录

						零件图		颜 色 COLOR		SCALE		1:1		WCON WCON Hardware Electronics Co.,Ltd						
						X.		材 质 MATERIAL		UNIT		mm								
						X.X	±0.10													
						X.XX	±0.05	设计 DESING		颜亚芳		08/05/10				SIZE	A4			
						X.XXX	±0.02													
						Angle		审 核 CHECK				SHEET		1/1		料 号 PART NO.		6210-XXMXXXB01		
A0	08/05/10	NEW					X.	± 2'	核 准 APPROVE						PROJ.		品 名 TITLE:		D-Sub Male XXP 3排 焊线式	
版次 REV	日期 DATE	变 更 说 明 MODIFICATION DESCRIPTION			变更 CHANGE	核 准 APPROVE	DIM	TOL												